



AIWA CO.,LTD

UTSUNOMIYA FACTORY

2620, TOKUJIROU-MACHI, UTSUNOMIYA-SHI, TOCHIGI 321-21, JAPAN

SERVICE TECHNICAL INFORMATION

ONE POINT REPAIR

UTSUNOMIYA, MAY 15, 1997

REF. NO.: SI-97-009

CUSTOMER RELATIONS & SERVICE DIV.

MODELS : NSX-V210 / V220 / V420 / V2100
SUBJECT : Service manual correction and DSP IC

CONTENTS : A mistake was discovered in the NSX-V210 Series Service Manual. The following is a correction of this mistake.

[NSX-V210 EZ, K, HR / NSX-V220 EZ] • • • • S/M Code No. 09-96C-173-6FP

* An incorrect name for the CD mechanism was printed on the cover of the Service Manual.

Incorrect → 4ZP-1 BDLNM
↓
Correct → 4ZG-1 BDLNM

* Refer to the 4ZG-1, A, B, Z Comprehensive Manual (Code No. 09-965-128-10T) Type [B] (models with a built-in Toshiba IC).

* The 4ZG-1 BDLNM equipped in NSX-V210, V220, and V2100 comes with a DSP IC (IC101). TC-9441F is used in this IC, but is also compatible with TC-9284F.

Part Name	Part No.	
IC TC9284F	(87-070-336-010)	Compatible Parts
IC TC9441F	(86-NFZ-669-010)	

Note: There are sets equipped with a 4ZG-1 ZDLNM that only have NSX-V2100 (U) specifications.