

**marantz®****Service Bulletin****No. : MZ07-102****Date: November 29, 2007****Model:** CD5400**Subject:** Correction of the Service Manual, Electrical Parts list.**Symptom:** The IC part number (POS.NO.IC62) mentioned on the CD5400's Service Manual is incorrect. (Service Manual page 40)**Solution:** Use the corrected part number listed below when ordering a replacement IC62.**Parts:**

OLD NEW	POS. NO.	VERS. COLOR	PART NO. (MZ)	PART NAME	DESCRIPTION
OLD	IC62		HC762837Z0	IC	T.I Factory code no. HVITC74LS628
NEW	IC62		90M-HC700560R	IC	TC74LS628 Factory code no. HVITC74LS628

Serial Number Range:

All

CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.