



Service Bulletin

No. : MZ01-004

Date: January 10, 2007

Model: CD6000, CD6000OSE

Subject: Change of CD mechanism and CD loader.

Symptom: CD mechanism and CD loader was changed.

Solution: CD mechanism and CD loader (with Disc clamper) was changed as follows:

Service code	CD mechanism	Clumper (color)	CD loader
SV00	VAM1201/01	GRAY	L1260/41
XE00	VAM1202/02	BLACK	L1260/61
XE01	VAM1201/11	GRAY	L1260/41
XE02	VAM1201/11	GRAY	L1260/45

When replacing the CD mechanism with the new one, please check the service modification code and refer to the following details:

1. If the service modification code is SV00, XE01, XE02 replace the CD mechanism with the new one VAM1201/11 (356K304500) only.
2. In case of service modification code XE00 Replace both the CD mechanism and the disc clamper with the new ones. VAM1201/11 (P/N 356K304500), disc clamper <GRAY> (P/N 305K005600).

CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.