



marantz®

Service Bulletin

No. : MZ02-028

Date: December 5, 2006

Model: CDR500

Subject: Improves playability of the discs recorded by Disc-At-Once mode.

Symptom: Disc stops playing or can't playback some tracks.

Solution: Update the DASP firmware version to [MAR.2.17]. Please refer to the Service manual MAR770/MAR775 and about details of updating the firmware.

Serial Number Range:

This improvement has been done in production after Lot number "23" and later. The Lot number is mentioned the serial number label on the rear panel.
(ex.MZxxxxxx23xxxx)

CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility is will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.