



**marantz®**

**Service Bulletin**

**No. : MZ09-101**

**Date:** October 6, 2009

---

**Model:** SA8003

**Subject:** Correction of the Firmware.

**Countermeasure is applicable only upon claim from the customer.**

**Symptom:** 1) iPhone cannot be connected.

- 2) Change of factory code of production number. (01→MZ)
- 3) When in resume mode, the track that was previously played is momentarily audible when the track is changed.
- 4) The connectivity with iPod touch is improved.

**Solution:** We corrected the firmware so that no malfunction occurs.

**MODIFICATION:**

Please refer to the Service Manual Software Version: **FR2009061902**

File Name: **SACD\_09061902.mot**

Check SUM: **11F 4CC4** (Range: 0~1FFF)

**Serial Number Range:**

**MZ000926000396 ~**

---

**CONFIDENTIALITY NOTICE:**

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.