



## **Service Bulletin**

**No. :** MZ05-034

**Date:** January 4, 2007

---

**Model:** SR5500

**Subject:** Correction of the Electrical parts list in the Service Manual.

**Symptom:** The part number for IC28 DSP PCB (CUP11706Z) mentioned in the SR5500's Service Manual is in correct (page 67).

**Solution:** See the corrected parts information below.

### **Parts:**

Ref #	FORMER		NEW	
	Description	Part Number	Description	Part Number
IC28	HD64F2398F20	90M- HS27AWH0R	U-PRO (FLASH)	90M- HS08BWH0R

---

#### **CONFIDENTIALITY NOTICE:**

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.