

| | | | |
|--|--------------|--------------------|----------------------|
| marantz® SERVICE BULLETIN | | Date: 15-May.-2003 | Model: SR7300,SR6300 |
| | | Page: 1 / 1 | REF.NBR: MZ03-018 |
| Subject: | | | |
| The problem that the remote controller can't lean other the remote controller . | | | |
| Circulation: | Application: | | |
| <input checked="" type="checkbox"/> for information customer complaint in case of service mandatory | See Below | | |
| | | Int.ref: | |

[PHENOMENON]

When learning and memorizing the remote control codes used by Set-top Box of Time Warner Inc.,
 A part of cursor button can't be learned.

[SOLUTION]

RC7300SR is exchanged for the improvement the remote controller RC7300SRa.

[NECESSARY PART]

Improvement the remote controller part no. **ZK03AJ0012**

(SR6300: old remote controller part no. ZK15AW0010 FACTORY PART NO.8300030010010)
 (SR7300: old remote controller part no. ZK03AJ0010)



Model name **RC7300SRa**

[REMARKS]

The countermeasure apply to this claim only.

This solution has already been applied in the production line after
 the Lot number “**MZxxxxxx27xxxx**” and later.

The production of SR6300 has been finished.

Approved by **S.NAGAO**

Written by

WQ-19 2 817/additional rule 3 (1st Issue 2003-03-19)