



Service Bulletin

No. : MZ08-009

Date: February 21, 2008

Model: SR7002, SR8002

Subject: Information about the first edition software

Symptom: This Software (firmware) was used during the mass production of this product.

Please refer to the service manual for "How to update Software".

*Flash ROM IC34, IC91 (With software).

Note: There is usually, no need to write-in this software. The replacement parts of IC's IC34 and IC91 have already had the software written to them.

Solution:

Software Version

Micro-processor POS.NO	TYPE	VERSION	REMARK	FILE NAME of Upload on marantz S.D.I	PART NO.
IC34	DSP	B1 10708201 B2 20708231	pa17_c78_070823_1.upd	00M36CW499C00.zip	-
IC91	HD Radio	-	SR8002_HdrV07082701.id SR8002_HdrV07082701.mot	00M36CW499D00.zip	-

The software of IC17 (Main) and IC81 (HDMI) was already changed from the first edition. Refer to Service Bulletin REF.NBR: **MZ07-098** (29-Oct-2007) for more information.

Serial Number Range:

All

CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.