

marantz®

Service Bulletin

No. : MZ10-052

Date: October 12, 2010

Model: SR7005

Subject: Adding a Knob spring.

Countermeasure is applicable only upon claim from the customer.

Symptom: The force of pulling of Volume/Selector knob might be weak.

Solution: Add the Knob spring to the knob shaft.

Insert SPRING to bottom of knob.



CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.

Parts:

Ref#	Description	Part Number
NA	SPRING	472310015007M

Serial Number Range:

Please apply the above modification to the production models in the following serial numbers.

20001029000018 ~ 20001034001617

CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.