
P100
P200
PX01
PB00
P400
PZ01
PC01
PU01
PS01
PE01
PT01
PR50
P900
P700 (L)
P700 (R)
PN01
PW01
P800
PD01
AM
FM
AM LOOP STICK ANT
PHONO 1
PHONO 2
AUX 1
AUX 2
TAPE 2
TAPE 1
DUBBING
SCOPE LAMP
STEREO
DIAL POINTER
GUARDRA OUT
FOCUS
BRIGHT
THERMOSTAT
SYSTEM 2
SYSTEM 1
PHONES
BALANCE
SCOPE DISPLAY

## 14. SCHEMATIC DIAGRAMS

### SCHEMATIC DIAGRAM – U.S.A. & CANADA