D&M
D&M Holdings Inc.
100 Corporate Drive Mahwah, NJ 07430

marantz®

Service Bulletin
No. : MZ09-034
Date: July 21, 2009

_____

Model: PM15S2

Subject: Service spare part addition information.

Symptom: The part number of Main Microprocessor (QU01) software was added to Service spare part. * Microprocessor needs writing software, when a microprocessor (QU01) is replaced

Solution: Download the firmware and write to the new microprocessor upon replacement.
Attention: Don't start from the zipped file. Please download a copy onto your PC and be sure to unzip it before using.

Parts:

Ref#	Description	Part Number
N/A	SOFTWARE for MAIN MICROPROCESSOR (QU01) v090507.mot	00M27AJ499A00

Serial Number Range:
All