

Service Technical Information

MODEL NO. XR-HG5MD
SUBJECT Notes on replacing μ -COM

REF.No. :G – A0 – 078– E0

DATE :25. SEP. 2000

<CONTENTS>

The CD mechanisms mounted on the models above are broadly divided into two different types.
 μ -COM used on the CD mechanisms are not compatible with each other on different types.

When replacing μ -COM, be sure to identify a CD mechanism with reference to the table below:

Determine a type of CD mechanism by a pick up that is mounted.

1. AZG-1 ZD3 / ZD4 KSS-213F is mounted
2. AZG-1 ZD8 KSM-880 is mounted

Servo (IC)	KSS-213F 	KSM-880 
Digital Servo (LA9235M, LC78641E)	8A-DB8-616-110 LC876580W-5R43	8A-DB8-616-010 LC876580W-5N90

Ref.	Parts Code	Description	Remarks
IC101	8A-DB8-616-010	C-IC,LC876580W-5N90	AZG-1 ZD8
IC101	8A-DB8-616-110	C-IC,LC876580W-5R43	AZG-1 ZD3 / ZD4

G	R	Code No.	Access Code	Modified Ser. No.	Parts Schedule
–	–	–	–	–	NOV.2000