



Service Bulletin

No. : MZ00-009

Date: November 29, 2006

Model: CD6000, CD6000OSE

Subject: Problem with the function "DELETE PROGRAMMING". Problem with the emphasis CD playback.

Symptom: 1. Problem with the function "DELETE PROGRAMMING".

When playing back the CD in the "DELETE PROGRAMMING" mode, If only one track is deleted, then the next track and all following tracks will not be played back. In case of several tracks are deleted, this phenomenon will not appear.

2. Problem with the emphasis CD play back.

When playback several emphasis CD's continuously, the second emphasis CD is played back without de-emphasis after the first emphasis CD has finished playing back.

Solution: Replace the microprocessor 7600 with the improved version.

Parts:

Ref#	Description	Part Number
7600	uPD7806GF-098-3BA	HU255WN03F

Serial Number Range: This improvement has been done in production after the service modification code number "XE02" and later. The lot number and the service modification code are mentioned in the serial number label on the rear panel. (ex. XE02 xxxxxxxxxxx).

CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.