

marantz®

Service Bulletin

No. : MZ03-052

Date: December 13, 2006

Model: CDR510

Subject: When recording from external sources, the last 2 seconds cannot be recorded.

Symptom: 1. Select "REC Ext MAN" recording mode, start recording.
2. Press the PAUSE button during recording.
3. Again press the PAUSE button then press REC button.
4. Press the PAUSE or STOP button, the last 2 seconds cannot be recorded

Solution: Replace MICRO PROCESSOR QU01 on the PS16-SERVO/MP3/CPU CIRCUIT BOARD.

First please check the version of QU01. The version number can be confirmed in SERVICE MODE, Refer to service manual page 14 for details.

7. SERVICE MODE

1. Turning into Service Mode

While pressing **STOP(CDR)** and **PLAY/PAUSE(CDR)** buttons, press **POWER** button.

Mode0,1,2 and 3 are CD Player side.

2. Mode 0 (display "VER_*-P00")**

Version number of The micro computer(QU01) is displayed (*-**).


0.25

CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.

Parts:

Ref#	Description	Part Number
QU01	Flash ROM MB90F574A	*HS12AKF3R

Serial Number Range:

This problem applies to the following Lot number. CDR510/N1B:
MZxxxxxx01xxxx to MZxxxxxx03xxxx. CDR510/U1B: MZxxxxxx01xxxx to
MZxxxxxx07xxxx.

CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.