



Service Bulletin

No. : MZ02-016

Date: December 4, 2006

Model: SR5200, SR6200, SR7200

Subject: The problem that No sound is out put when AUDIO signal is changed from AC-3 to PCM.

Symptom: When the SET is connected to a DVD Player (DV4200, DV6200, VC5200) no sound is out put when the AUDIO signal is changed from AC-3 to PCM.

Solution: Replace MICRO PROCESSOR (OPT) IC107 on the MAIN CIRCUIT BOARD.

Parts:

Ref#	Description	Part Number
IC107	CXP7400P100-1 QFP	*HU100600R

Serial Number Range:

The countermeasure applies only to this type of problem.

CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility is will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.