


Model: SR7001

Subject: Part Change: OPT/COAX Complex Jack (both TX/RX)

Symptom: The manufacturer has discontinued production of the current parts.

Solution: 1. POS.NO. (JK11, JK12, JK13 and JK14) on the DSP PWB are the parts whose specifications have been changed this time.



CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.

2. Due to the configuration differences, the new parts are incompatible with the old ones. Please note that the INPUT PWB and REAR PANEL have to be replaced.

Parts:

OLD NEW	POS. NO.	PART NO. (FOR EUR)	PART NO. (MZ)	PART NAME	DESCRIPTION
OLD	JK11 JK12 JK13	90M-YT004060R	90M-YT004060R	TERMINAL	YKC22-0735N
NEW	JK11 JK12 JK13	90M-YT005330R	90M-YT005330R	TERMINAL	YKC22-0836V
OLD	JK14	90M-YT004070R	90M-YT004070R	TERMINAL	YKC22-0734N
NEW	JK14	90M-YT005340R	90M-YT005340R	TERMINAL	YKC22-0835V
OLD	61	nsp	nsp	PANEL	SR7001 REAR PANEL U
NEW	61	nsp	00M05CW250160	PANEL	SR7001 REAR PANEL U

Serial Number Range:

The part specification change applies to the following serial numbers:
MZ0207XX005401~

CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.