



Service Bulletin

No. : MZ10-053

Date: September 30, 2010

Model: SR7005

Subject: Modification of the Firmware via DPMS (D&M Product Management Server).

Countermeasure is applicable only upon claim from the customer.

Symptom: 1) To add the "Wizz APP" function for iPhone/iPod.
2) Phenomenon with SR7005 Receiver in combination with Control4 Installations:
After power failure, SR7005 does not reconnect.

Solution: We corrected the firmware so that no malfunction occurs.

Updating the firmware (Refer to the Instruction Manual.)

Time necessary for update: approximately 10 min.

METHOD OF UPDATING the firmware via RS232C.

We will supply the following program files for updating the subject models in SDI.

Please refer to the following Instruction Manual for updating.

Time necessary for update: approximately 40 min.

DFW software:

DFW_0005_SR7005 (Rev.1.0.13).exe:

Firmware Update Program for ALL

DFW_0005_SR7005_Rev.1.0.13_Manual_EN.pdf: Instruction Manual for
Firmware Update Program for ALL

CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.

Firmware:
SR7005_U_MZ10-053.zip

SR7005

| | Name | Version |
|------|---------------|--------------|
| 1 | Main | 93.55 |
| 2 | Main FBL | 00.10 |
| 3 | Sub | 27.17 |
| 4 | Sub FBL | 05.01 |
| 5 | DSP | 60.06 |
| 6 | Audio PLD | 05.02 |
| 7 | OSD CFG | 200912070011 |
| 8 | OSD PRG | 201006111006 |
| 9 | OSD DAT | 201006111008 |
| 10 | DM860 SBL | 201002081213 |
| 11 | Main | 93.55 |
| 12-1 | DM860 IMG (U) | 201009100618 |
| 12-2 | DM861 IMG (N) | 201009100722 |
| 12-3 | DM862 IMG (K) | 201009100950 |

Serial Number Range:

We will apply the above modification to the production models in the following serial numbers.

20001040***** ~ (From October 2010 production)

CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.