

marantz®

Service Bulletin

No. : MZ07-092

Date: October 17, 2007

Model: SR7400


Subject: Service Manual parts correction for 18000uF ELECT. CAP.

Symptom: The part number for ELECT.CAP 18000uF (POS. NO.C633 / C634) is incorrect in the Service Manual (Service Manual page 100)

Solution: The Old Part number: EB10907170 is for a 10,000uF cap. It cannot be used for POS.NO.C633 / C634. Use P/N: 90M-EB000060R (18,000 uF).

Parts:

OLD NEW	POS. NO.	VERS. COLOR	PART NO. (FOR EUR)	PART NO. (MZ)	PART NAME	DESCRIPTION
OLD	C633 C634		EB10907170 (00MEB10907170)	EB10907170 (00MEB10907170)	ELECT.CAP	DL71VN 18000(M) Factory code no. HCET71VDL183N
NEW	C633 C634		90M-EB000060R	90M-EB000060R	ELECT.CAP	DL71VN 18000(M) Factory code no. HCET71VDL183N



CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.