

Service Bulletin

No. : MZ07-045


Date: March 28, 2007

Model: SR6001, SR7001, SR8001

Subject: Service spare part addition information.

Symptom: The part number of HDMI PWB ASSY was added to Service spare part.

Solution: The HDMI PWB part number was added (see the parts section).



CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.

Parts:

Ref#	Description	Part Number
56	HDMI PWB ASSY (SR6001)	90M-ZZ004550R
56	HDMI PWB ASSY (SR7001)	90M-ZZ004530R
56	HDMI PWB ASSY (SR8001)	90M-ZZ004540R

CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.