




TERMINALS OF P1	FUNCTION
1 & 2	INPUT
3	B-
4	CT INPUT
5	B+
7	METERING +
11 & 12	OUTPUT
14 & 15	HEATER

TRANSFORMER CONNECTIONS		
IMPEDANCE	INPUT - T1	OUTPUT - T2
37.5 OHMS	1-5, 2-6	
150 OHMS	1-3, 4-C.T.	7-8, 9-10
600 OHMS	3-4, 3 C.T.	8-9


ALL RESISTANCES IN OHMS AND
ALL CAPACITANCES IN MICROFARADS
UNLESS OTHERWISE INDICATED.

748999-4

RCA BA-21A

Figure 4—Schematic Diagram

Figure 4 - Schematic Diagram



ALL RESISTANCES IN OHMS $\frac{1}{2}$ WATT, AND
ALL CAPACITANCES IN MICROFARADS
UNLESS OTHERWISE INDICATED.
ARROWS AT P1 INDICATE PHASING

634821-2