

| | | | |
|--------------------------------------------|--------------|----------------------------------------------------------------------------------------------|------------------------------|
| marantz® SERVICE BULLETIN | | Date: 21-Feb.-2007 | Model: PM4001,PM4001F |
| | | Page: 1 / 2 | REF.NBR: MZ07-019 2nd |
| Level | Application: | The Remote Controller is changed. Main Transformer thermal fuse is changed. | |
| ★ | See below | | |
| | | Int.ref: | |

[REASONS]

The Remote Controller is changed in order to use it in common with other System by marketing request.
 Improve Main Transformer reliability.

[SOLUTION]

1. Replace the Remote Controller (From RC4001PM to **RC002PM**).
 RC002PM TUNER selection RC code is not same as RC4001PM.
 Therefore RC002PM can not use PM4001 and PM4001F with the Serial no. service code "MZ00" to "MZ02".
2. Change Main Transformer thermal fuse.

[NECESSARY PART]

2nd: User Guide part no was added

| OLD NEW | POS. NO. | VERS. COLOR | PART NO. (FOR EUR) | PART NO. (MZ) | PART NAME | DESCRIPTION |
|------------|-------------|----------------------|-----------------------|----------------------|-----------------------|------------------------------------------------------------------------------|
| OLD | | /N1B /N1G /N1S | 3070100010088 | 3070100010088 | UNIT KIT | REMOTE CONTROLLER RC4001PM Factory code no. HARTPM4001 |
| NEW | | /N1B /N1G /N1S | 00MZK26CW0010 | 00MZK26CW0010 | UNIT KIT | REMOTE CONTROLLER RC002PM Factory code no. CARTPM4001RC |
| OLD | TRS2 | /N1B /N1G /N1S | 90M-TS002540R | 90M-TS002540R | TRANSF. | ! TRANS, POWER FOR N Factory code no. CLT5R028YW |
| NEW | TRS2 | /N1B /N1G /N1S | 90M-TS003140R | 90M-TS003140R | TRANSF. | ! TRANS, POWER FOR N Factory code no. CLT5R028XW |
| OLD | | /N1B /N1G /N1S | 00M44BW851310 | 00M44BW851310 | USER GUIDE | USER GUIDE PM4001 / PM4001F Factory code no. CQX1A1034Z |
| NEW | | /N1B /N1G /N1S | 00M44BW851313 | 00M44BW851313 | USER GUIDE | USER GUIDE PM4001 / PM4001F Factory code no. CQX1A1034Y |

[REMARKS]

The remote controller and Transformer which were changed following Serial no. (service code).

1) PM4001/N1B/N1S/N1G

This change has been done in the production serial number **MZ03xxxxxxxxxx and after.**

2) PM4001F (PM4001 OSE) /N1B/N1S

This change has been done in the production serial number **MZ03xxxxxxxxxx and after.**

NEW RC002PM



OLD RC4001PM



NEW RC002PM



OLD RC4001PM

