

Service Manual

ORDER NO.
RRV2961

DVD/CD RECEIVER

XV-DV8

THIS MANUAL IS APPLICABLE TO THE FOLLOWING MODEL(S) AND TYPE(S).

Model	Type	Power Requirement	Region No.	Remarks
XV-DV8	LFXJ	AC110- 120V	3	-

- This service manual should be used together with the following manual(s).

Model No.	Order No.	Remarks
XV-DV8/DLXJ/NC	RRV2908	

PIONEER CORPORATION 4-1, Meguro 1-chome, Meguro-ku, Tokyo 153-8654, Japan

PIONEER ELECTRONICS (USA) INC. P.O. Box 1760, Long Beach, CA 90801-1760, U.S.A.

PIONEER EUROPE NV Haven 1087, Keetberglaan 1, 9120 Melsele, Belgium

PIONEER ELECTRONICS ASIACENTRE PTE. LTD. 253 Alexandra Road, #04-01, Singapore 159936

©PIONEER CORPORATION 2004

1. CONTRAST OF MISCELLANEOUS PARTS

A

NOTES:

- Parts marked by "NSP" are generally unavailable because they are not in our Master Spare Parts List.
- The \triangle mark found on some component parts indicates the importance of the safety factor of the part. Therefore, when replacing, be sure to use parts of identical designation.
- Screws adjacent to ∇ mark on product are used for disassembly.
- For the applying amount of lubricants or glue, follow the instructions in this manual. (In the case of no amount instructions, apply as you think it appropriate.)
- Reference Nos. indicate the pages and Nos. in the service manual for the base model.

■ CONTRAST OF TABLE


B XV-DV8/LFXJ and /DLXJ/NC are constructed the same except for the following:

Ref. No.	Mark	Symbol and Description	Part No.		Remarks
			XV-DV8 /DLXJ/NC	XV-DV8 /LFXJ	
P9- 7	NSP	<PCB ASSEMBLIES> COMPLEX ASSY PRIMARY ASSY	XWM3237 XWZ3845	XWM3238 XWZ3859	
P7- 1 P7-15	\triangle	<PACKING> AC Power Cord Packing Case (English/Trad-Chinese)	ADG1154 XHD3424	ADG7098 XHD3420	
P9-14 P9-15	\triangle \triangle	<EXTERIOR SECTION> Power Transformer(T1) Fuse (FU 1)	ATS7355 REK1029 (5.0A/250V)	ATS7354 REK1069 (6.3A/125V)	
P9-22 P9-45		Rear Panel (MTL) Caution Label Region Label	XNC3275 VRW1872 Not used	XNC3278 VRW1961 VRW1702	No. 1
P11- 7		<FRONT PANEL SECTION> Display Window	XAK3447	XAK3447	

C Notes : ● The numbers in the remarks column correspond to the numbers on the " EXPLODED VIEWS ".

● For PCB ASSEMBLIES, Refer to "CONTRAST OF PCB ASSEMBLIES" and "2. SCHEMATIC DIAGRAM".

■ EXPLODED VIEWS
● EXTERIOR SECTIONS



■ CONTRAST OF PCB ASSEMBLIES




KF PRIMARY ASSY

XWZ3859 and XWZ3845 are constructed the same except for the following :

Mark	Symbol and Description	Part No.		Remarks
		XWZ3845	XWZ3859	
	T002 Stand by Transformer (T 2) AN01 1P AC INLET CN 02 5P-VH Connector S0101,S0102 Voltage Selector	ATT7080 XKP3041 B5P9-VH AKX7017	ATT7079 XKP3042 Not used Not used	

2. SCHEMATIC DIAGRAM

2.1 PRIMARY and VIDEO JACK ASSYS





CAUTION
FOR CONTINUED PROTECTION
AGAINST RISK OF FIRE.
REPLACE WITH SAME TYPE
AND RATINGS OF FUSE.

- (AD) : AUDIO DATA SIGNAL ROUTE
- (FL) : AUDIO SIGNAL ROUTE (Front L ch)
- (SL) : AUDIO SIGNAL ROUTE (Surround L ch)
- (C) : AUDIO SIGNAL ROUTE (Center ch)
- (SW) : AUDIO SIGNAL ROUTE (Sub Woofer ch)

• NOTE FOR FUSE REPLACEMENT

CAUTION -FOR CONTINUED PROTECTION AGAINST RISK OF FIRE.
REPLACE WITH SAME TYPE AND RATINGS OF FUSE.

K F M N



'to AF ASSY CN11)

D 4/4 CN52 or CN51

K F O