

Date 04.04.03	Ref. No. 03AH001	Model SX-LX7, XR-X7	TD
Subject Part number for "Stand, Speaker"			IRIS

SYMPTOM

The "Stand, Speaker" is not listed in the parts list on page 55 of the Service Manual.

SOLUTION

The correct part number for the "**Stand, Speaker**" is **U-006-6330-U**.

